

Specifications / Layout

No	Item		Specification	
1	Model		HDC-40i	HDC-35i
2	Input	Electric	AC110VC or AC220V, 50~60Hz	
		Air Pressure	Min 4.5 bar / Max 6 bar	
3	Output	Electric	DC40V, 3A	DC35V, 4A
4	Fuse		AC250V, 10A	AC250V, 15A
5	Dimension		Refer the dimension above	
6	Preset Parameters		Torque, Speed and Angle are possible to control and set by 8 presets	
7	Preset control methods		Buttons on the controller 25P I/O interface 8 Sensors which have connected via I/O Ports F1 button on HD driver	
8	Error display		Errors display on the FND screen by error numbers	
9	OK/NG judgement of screwing		OK/NG judgement of screwing is possible by number of turns, torque and times	
10	Monitoring		Real time monitoring and graph monitoring are available via Hi manager (Dedicated Software)	
11	Communication Port		USB, RS232C	



Unit : mm